

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6





FIG. 7


PAGES: ☒ ALL ☐ 1 ▼ ↔ 1 ▼ 701

COPIES: 1 ▼ 702

AUTO RETREAT FLAG: ON ☒ OFF ☐ 703

PAPER SIZE: A4 ▼ 704

STAPLING: YES ☐ NO ☒ 705

DOUBLE-SIDED: ON ☐ OFF ☒ 706

CANCEL 708 PRINT 707

FIG. 8

B5 PAPER(S) IS/ARE ABSENT IN DESIGNATED PAPER SUPPLY,
 SO YOUR PRINTING IS SUSPENDED AND PRINT DATA IS
 RETREATED IN PRINTER. PRINTING WILL BE RESUMED UPON
 SETTING B5 PAPER(S). UNTIL THEN, OTHER PRINT DATA IN
 SPOOL IS PROCESSED FIRST.

OK

FIG. 9




FIG. 10

[illegible]

JOB EXECUTION MANAGEMENT TABLE D

NO.	ID	JOB	OWNER	PRINT DATA	JOB ATTRIBUTE	STATUS	:
2	ID=981010-40	SAMPLE-C	B	¥FILE-B2	A3/SINGLE-SIDED/STAPLING/...	WAITING	:

FIG. 11D

JOB EXECUTION MANAGEMENT TABLE E

NO.	ID	JOB	OWNER	PRINT DATA	JOB ATTRIBUTE	STATUS	:
1	ID=981010-20	SAMPLE-B	B	¥FILE-B1	B5/SINGLE-SIDED/NO STAPLING/...	PRINTING	:

FIG. 11E

JOB EXECUTION MANAGEMENT TABLE F

NO.	ID	JOB	OWNER	PRINT DATA	JOB ATTRIBUTE	STATUS	:
1	ID=981010-40	SAMPLE-C	B	¥FILE-B2	A3/SINGLE-SIDED/STAPLING/...	PRINTING	:

FIG. 11F

JOB RETREAT MANAGEMENT TABLE A

NO.	ID	JOB	OWNER	PRINT DATA	JOB ATTRIBUTE	STATUS	:
1	ID=981010-20	SAMPLE-B	B	¥FILE-B1	B5/SINGLE-SIDED/NO STAPLING/...	RETREATED	:

FIG. 12A

JOB RETREAT MANAGEMENT TABLE B

NO.	ID	JOB	OWNER	PRINT DATA	JOB ATTRIBUTE	STATUS	:
1	ID=981010-20	SAMPLE-B	B	¥FILE-B1	B5/SINGLE-SIDED/NO STAPLING/...	RETREATED	:
2	ID=981010-40	SAMPLE-C	B	¥FILE-B2	A3/SINGLE-SIDED/STAPLING/...	RETREATED	:

FIG. 12B

JOB RETREAT MANAGEMENT TABLE C

NO.	ID	JOB	OWNER	PRINT DATA	JOB ATTRIBUTE	STATUS	:
1	ID=981010-40	SAMPLE-C	B	¥FILE-B2	A3/SINGLE-SIDED/STAPLING/...	RETREATED	:

FIG. 12C

FIG. 13

AUTO RETREAT INFO TABLE

ITEM	CONTENTS
NO PAPER	NO PAPER OF DESIGNATED SIZE
NO STAPLE	NO STAPLE FOR STAPLING
PORT-FULL	EJECTION PORT IS FULL OF PRINTED PAPERS; FURTHER EJECTION IS IMPOSSIBLE
PORT-PAPER	PRINTED PAPER(S) IS/ARE IN EJECTION PORT; FURTHER EJECTION WILL CAUSE MIXED PAPERS
TONER-LOW	TONER AMOUNT IS LOW; PRINT QUALITY WILL BE POOR
:	:


FIG. 14

FIG. 15




FIG. 16




FIG. 17




FIG. 18